

Commercial
Since 1976

Grab 'em Paint



353727s

The Rebuilding Maintenance Paint™ for Most Surfaces

GALVANIZED STEEL QUONSET; ROLLA, MO; ERECTED 1983, PAINTED 1986

AREAS

SECTION: 1 2 3 4 5 6

A — [

B — [

C — [



**29 Years
Proves
The Value
Of
Grab 'Em
Primers
& Finish
Coats**



Areas

- 1-A No paint - galvanizing failed with iron rust >5% of the surface.
- 1-B Primer looks good but thin coat. Some iron corrosion on bolt heads.
- 1-C **Excellent** - smooth gray color. Some iron corrosion on bolt heads.
- 2-A Nearly Perfect in all areas (a little thin on A) **No corrosion** over White topcoat 439.
- 2-B White topcoat 439 over White Primer 606. **No Corrosion.**
- 2-C White topcoat 439 over Gray Primer 450. No Corrosion.
- 3- Omit
- 4-A Cheap Aluminum-Asphalt Paint gone in 1 year. Result severe corrosion on flat steel & bolts.
- 4-B White Primer 606 **Good**. May be rust staining from above.
- 4-C Gray Primer 450 **Excellent. No Corrosion.**
- 5-A Medium Aluminum-Asphalt Paint gone in 4 years. Results severe corrosion on steel & bolts.
- 5-B White Primer 606 **Good** but thin after 29 years.
- 5-C Gray Primer 450 **Excellent. No Corrosion.**
- 6-A High quality Aluminum-Synthetic resin paint - peeling at 7 years. Severe peeling at 29 years.
- 6-B White Primer 606 + Al finish. **Excellent, No peeling, No Failure at 29 years.**
- 6-C Gray Primer 450 + Al finish. **Excellent. No peeling at 29 years.**

Wienert Manufacturing Co.

(see website at Grab-emPaint.com or WienertMfg.com)

LESTER A. WIENERT

(Owner, 39 yrs.)

LesterWienert@centurytel.net

ACS (50yr), NACE, SSPC, ASTM FSCT
21 years seeking new paint fungicides
plus 39 years of commercial paint
production

ROBERT J. WIENERT

(Chemical Engineer
Consultant, 4 yrs.)

RJWienert@centurytel.net

AICHe, NACE, AESF, SSPC
19 years of Electroplating Circuits



Factory:
277 State Hwy. 64
Louisburg, MO 65685
417-752-3210

Office: HC 79,
Box 3063A
Pittsburg, MO 65724
(Road 356 off TT)
417-852-1211